FIG. 1(A)




FIG. 1(B)




FIG. 2(A)

Surface roughness		
Ra	$[\mu m]$	0. 29
Ry	$[\mu m]$	2. 17
Rz	$[\mu m]$	1. 70
δ	$[\mu m]$	1.05
tp	[%]	36. 72
Sm	$[\mu m]$	6. 75
S	$[\mu m]$	1.34
RMS	$[\mu m]$	0.36
Cut	[mm]	non

Measurement condition				
cessed				
cessed				
$\pm$ 2				





FIG. 2(B)

Surfa		
Ra	$[\mu m]$	0. 30
Ry	$[\mu m]$	2. 18
Rz	$[\mu m]$	1.83
δ	$[\mu m]$	1. 15
tp	[%]	27. 34
Sm	$[\mu m]$	7. 21
S	$[\mu m]$	2. 20
RMS	$[\mu m]$	0. 38
Cut	[mm]	non

Measurement condition				
		non processed		
Bright cut	:	non processed		
Smoothing		$simple \pm 2$		
Inclination correction		Auto		






FIG. 3 (B)




FIG. 3 (C)

